

405/01-332 Mine F.I.B.
S. L. LinnRECEIVED
NOV 20 19863400
(SL-062648)
(U-066)Moab District
Price River Resource Area
P. O. Drawer AB
Price, Utah 84501DIVISION OF
OIL, GAS & MININGCERTIFIED MAIL--RETURN RECEIPT REQUESTED
Certification No. P 241 127 504Mr. Charles Gent
Genwal Coal Company, Inc.
P. O. Box 1201
Huntington, Utah 84528

NOV 4 1986

Dear Mr. Gent:

This letter is sent as a Notice of Noncompliance for a violation of your approved mine plan as defined in 43 CFR 3486.3. It was observed that the North Mains had been driven beyond the approved incidental boundary line change, which allowed you to mine 10 acres in the Tract 2 part of your Federal coal lease SL-062648 prior to formal approval of the whole.

You are ordered to immediately cease mining in lands outside of the approved permit boundary lines until you have received formal approval to do so by OSM and/or DOGM, as appropriate.

A report will be written by BLM of the action taken by Genwal upon correction of this violation, which will result when you have obtained approval of the Tract 2 part of the mine plan or have an approved change in the 10-acre incidental boundary line which would allow for continued mining in the North Mains.

Failure to comply with the requirements of this Notice of Noncompliance may result in an order to cease mining operations, the initiation of cancellation proceedings, forfeiture of the bond, or all of the above.

Genwal is advised of the right of appeal in accordance with 43 CFR Part 4.

If you have any questions please contact Allen Vance of my staff at 637-4584.

Sincerely yours,

Area Manager

cc:
RDO (U-065)
USO (U-921)DOGM, Salt Lake City
OSM, DenverAVance:ds:10/31/86
Wang:0344D

*DISCUSSED w/Vance by phone 11-18-86
Fract II is less than the 10 acre bond allowed in
the Mining into I.B.C.
(2) Discussed w/ A. King (telephone) 11-20-86: Genwal has complied with
order of not mining. Genwal will submit amend. of mine segment
maps. (3) DOGM will process amendment of mine segment
change. LRB 11-20-86*